

DATA

ALBERT BRAY

POINTS / REPERES ESSENTIELS DES PROCEDURES

Waypoints / Procedures main fixes

Identification	Coordonnées <i>Coordinates</i>		RNAV	CONV	SID STAR	IAC
CMB	REF ENR 4.1		X		X	
ABY	REF AD 2 LFAQ.19		X	X	X	X
BANTI	REF ENR 4.4		X		X	
IZUKE	REF ENR 4.4		X		X	X
OGLIB	REF ENR 4.4		X			X
PERON	REF ENR 4.4		X		X	
RAWHI	REF ENR 4.4		X			X
ROGEV	REF ENR 4.4		X		X	X
SULEX	REF ENR 4.4		X		X	
XORBI	REF ENR 4.4		X		X	
←						
←						
AQ410	50°03'34.0" N	002°39'09.5" E	X			X
AQ510	49°57'49.3" N	002°34'28.1" E	X			X
AQ512	50°02'48.0" N	002°33'49.8" E	X		X	X
AQ514	49°58'11.1" N	002°41'18.6" E	X			X
AQ516	50°03'20.8" N	002°40'21.9" E	X			X
FAQ08	49°57'28.3" N	002°28'05.0" E	X			X
FAQ26	49°58'55.0" N	002°55'10.0" E	X			X
RW08	49°58'09.57" N	002°40'43.31" E	X			X
RW26	49°58'15.44" N	002°42'33.32" E	X			X