

**APPROCHE AUX INSTRUMENTS**

**TOUSSUS LE NOBLE**

Instrument approach  
CAT A B C

INA CONV ODILO 6D RWY 25R  
INA CONV ODILO 6M RWY 25R

**FREQ :** Voir/See AD 2 LFPN COM 01  
Absence ATS : **A/A** FR uniquement. Obtenir le QNH auprès de ATIS ORLY  
**A/A** FR only. Obtain QNH on ATIS ORLY

VAR  
1° E  
(20)

← Procédure sur clairance ATC  
Procedure on clearance ATC

